

Digital hygro-thermometer set with USB interface

Product Number EP0201040



Product Description

Digital hygro-thermometer set incl. USB

Digital hygro/thermometer set incl. USB 100 interface converter for individual programming of the recording period with integrated humidity/temperature sensor. For rapid measurement of temperature and humidity. The measuring ranges are -25.0 ... 60.0 °C and 0 - 100 % RH.

Measuring range:

- 0 - 100 % RH
- -25 to +60 °C